













Attributes	Benefits	
Low width-to-depth ratio	Low torsional effects	
Low height-to-base width/depth ratio	Low overturning effects	
Similar storey heights	Elimination of weak/soft storey	
Short spans	Low unit stress and deformation	
Symmetrical plan shape	Elimination/reduction of torsion	
Identical resistance on both axes	Balanced resistance in all directions	
Uniform plan/elevation stiffness	Elimination of stress concentrations	
Uniform plan/elevation resistance	Elimination of stress concentrations	
Uniform plan/elevation ductility	High energy dissipation	
Perimeter lateral resisting systems	High torsional resistance potential	
Redundancy	High plastic redistribution	
Direct load path, no cantilevers	Elimination of stress concentration	





















### **Common Failures caused by Irregularities** (Cont'd)



View inside the above building showing the collapse of the second story due to shear failure of the second-floor columns. Note the lateral displacement (interstory drift to the right) due to the torsional rotation of the upper part of the building.

Addis Ababa University (Dr. Adil Z.)

**Common Failures caused by Irregularities** (Cont'd)



Close-up of one of the collapsed columns of the above slide. Note that the upper floor has displaced to the right and dropped, and the top and bottom sections of the column are now side-byside. Although the columns had lateral reinforcement (ties) these were not enough and at inadequate spacing to resist the shear force developed due to the torsional moment which originated in the second story.

27 December 2017

Addis Ababa University (Dr. Adil Z.)

20

19













### **Uniform Mass Distribution (Cont'd)**



Damage to a wooden house due to a heavy roof supported on a flexible frame. 1971 San Fernando Earthquake.

Damage to the old portion of the Olive View Hospital in the 1971 San Fernando Earthquake. This building had a very heavy tile roof supported on unreinforced brick masonry and was neither designed nor detailed to resist seismic effects

27 December 2017

Addis Ababa University (Dr. Adil Z.)

# **Uniform Stiffness Distribution**



Olive View Hospital, Psychiatric Unit, San Fernando, California. 1971 San Fernando Earthquake. This unit was a 2-story reinforced concrete building. The structural system was a moment resisting frame. However, in the second story there were masonry walls that added significantly to the stiffness of this story.

Lightweight concrete was used in the construction of this building. Note that the building collapsed completely at the first (soft) story and the second floor dropped to the ground after moving laterally about 2 meters
 27 December 2017 Addis Ababa University (Dr. Adil Z.)

28

27



### Uniform Stiffness Distribution (Cont'd) View of the first story columns located in the east end of the building. Note that the explosive type of failure just above the ground and the offset between the columns and the solid shear wall. Close-up of the failure at the bottom of the column at the southeast corner of the building. The failure occurred in the zone of the column where there was not adequate confinement of the concrete and shear reinforcing steel. 27 December 2017 Addis Ababa University (Dr. Adil Z.) 30













## Multiple defense lines (Cont'd)

- The structural system, which can be considered as a combination of the ductile walls with a framed tube, is an excellent system for seismic-resistant design, providing several lines of defense whereby the behavior of the whole system can accommodate the demands of a severe earthquake.
- View of the core service walls and floor area at the second story of the Banco de America, Managua, Nicaragua. Note that few of the marble tiles that cover the reinforced concrete shear walls have spalled off. This was the only visible damage in this story after the 1972 Managua Earthquake.





37

27 December 2017

Addis Ababa University (Dr. Adil Z.)









#### Balanced stiffness, strength and ductility (Cont'd) Four Season Apartment Building, Anchorage, Alaska, 1964 Alaska EQ. General view of the building after the EQ. The lateral resistance to earthquake ground motions was essentially provided by the two slender vertical reinforced concrete shafts. These shafts failed at the ground floor level where all the vertical reinforcing bars in the shafts were spliced Overall view of an Apartment Building, Anchorage, Alaska, 1964 Alaska EQ. This 14-story RC structure has as a basic lateralresisting structural system a series of slender walls coupled by spandrel girders worked that as coupling Unfortunately these spandrel girders. girders were not designed (detailed) to work as coupling girders and therefore suffered significant damage in the EQ. Addis Ababa University (Dr. Adil Z.) 27 December 2017 42

43



- High ductility
- High strength-to-weight ratio
- Homogeneity
- Ease in making full-strength connections
- Possibility of suppression of brittle failure modes

27 December 2017

Addis Ababa University (Dr. Adil Z.)

Typical brittle failure modes of common		
construction materials		

Material of construction	Brittle failure mode	
Reinforced Concrete	Buckling of reinforcement bars Bond or anchorage failure Member shear failure	
Masonry	Out-of-plane bending failure Global buckling of walls Sliding shear	
Structural Steel	Fracture of welds and/of parent material Bolt shear or tension failure Member buckling Member tension failure Member shear failure	
27 December 2017 Addis	Ababa University (Dr. Adil Z.) 44	

Suitable Construction Material for Moderate to			
High EQ Loading			

	Type of building			
	High-rise	Medium-rise	Low-rise	
Best Structural materials in approximate order of suitability Worst	<ol> <li>(1) Steel</li> <li>(2) In situ reinforced concrete</li> </ol>	<ol> <li>Steel</li> <li><i>In situ</i> reinforced concrete</li> <li>Good precast concrete<sup>1</sup></li> <li>Prestressed concrete</li> <li>Good reinforced masonry<sup>1</sup></li> </ol>	<ol> <li>Timber</li> <li>In situ reinforced concrete</li> <li>Steel</li> <li>Prestressed concrete</li> <li>Good reinforced masonry</li> <li>Precast concrete</li> <li>Primitive reinforced masonry</li> </ol>	
<sup>1</sup> These two materials earthquake engineers	only just qualify for in would not use either mat	clusion in the medium-r erial in these circumstanc	ise bracket. Indeed, some es.	
	Dorwick	2009		
27 December 2017	Addis Ababa U	niversity (Dr. Adil Z.)	45	







### Codes improving, but not perfect ...

Uneven performance of model code-compliant buildings noted in recent earthquakes. Some perform very well, while others are inadequate.

- ✓ Nearly 70% of new steel buildings shaken by the Northridge earthquake suffered brittle fractures in their welded beam to column connections. More than 10% of new steel welded moment frame buildings in Kobe <u>collapsed</u>.
- Several new reinforced concrete structures collapsed or were severely damaged during the Northridge and Loma Prieta earthquakes.
- Important buildings designed by well respected engineers, under stringent quality control conditions are frequently damaged.

27 December 2017



Architect – Engineer Relationship
 While the provision of earthquake resistance is accomplished through structural means, the architectural design and the decision that create it, play a major role in determining the building's seismic performance
 Seismic design is a shared architectural and engineering responsibility, which stem from the physical relationship between architectural forms and structural systems.
 The interrelation between issues of engineering and architecture demand that architect and engineer work together from the inception of the project.



